

## **Technical Bulletin**

Bulletin No.

15-010

Issue Date:

22<sup>nd</sup> October 2015

Issue/Revision:

1

No. of Pages:

Prepared By:

**James Hargreaves** 

## IMPORTANT NOTICE TO ALL OWNERS OF SONARDYNE SURFACE COMMAND UNIT v.1s (SCU) & SCOUT SCU SYSTEMS MANUFACTURED PRIOR TO MAY 2011

Dear Valued Customer,

The SCU v.1 (8039) product, launched in August 2005, has now become obsolete due to component obsolescence. Limited operational support will be offered, however, servicing and repair will be withdrawn from this point onward.

The SCU v.1 forms a crucial component part of Scout systems manufactured prior to May 2011, although this system has already been previously announced as obsolete and superseded by a later generation system that does not utilise the SCU v.1. This provides customers with a low risk upgrade path to the latest tried and tested systems.

The table below shows the SCU based system and the current replacement system:

Obsolete SCU based system	Current replacement system
SCU v.1	SCU v.2
Scout SCU Systems manufactured prior to May 2011	Any Scout Portable system

Should you require any further clarification please contact customer support on <a href="mailto:support@sonardyne.com">support@sonardyne.com</a> or +44 1252 872288.

Yours faithfully,

Tim Moore

**Operations Director** 

